



Download Report

Download Certificate



C O M P R E H E N S I V E V E H I C L E C O N D I T I O N



Cosmetic
Body Score

S

95

Current Vehicle Condition

 No Damage Found

Previous Vehicle History

 Minor Cosmetic R

Vehicle Details

VIN	W
Year	
Make	
Model	4 Series 430i
Mileage	

Inspection Details


ID #
Date
Technician

TRUE360 reports are engineered to identify prior repairs or existing cosmetic damage to exterior body panels. This report is based on a visual inspection for vehicles that have, or have not reported accident history. In addition, when structural damage is identified as previously repaired, we will document these areas in an easy to read photo identified explanation. Modifications or damage to this vehicle that occur after the inspection date will not be reflected in this report. This report reflects the vehicle's cosmetic and topside structural condition as of the inspection date listed on the report. This report is not an evaluation of the vehicle's underbody structural, mechanical or interior condition and in no way guarantees that all prior repairs or existing damage will be identified.

TR
Conc

Cosmetic Inspection

The highlighted points on this vehicle diagram indicate the general areas where our inspection found prior repairs. These issues are not structural in nature and are considered to be purely cosmetic. Please be aware that this diagram may not be identical in appearance to the actual vehicle being inspected.



Exterior Body Inspection (Cosmetic)

Front Bumper Cover

Refinished

Hood

Original

Left Fender

Original

Left Front Door

Original

Left Rear Door

Original

Left Cosmetic Rocker

Original

Left Cab Corner

Not Applicable

Left Quarter Panel

Original

Left Bedside

Not Applicable

Roof

Original

Left Roof Rail

Original

Right Roof Rail

Original

Rear Bumper Cover

Original

Deck / Tailgate

Original

Right Fender

Refinished

Right Front Door

Refinished

Right Rear Door

Original

Right Cosmetic Rocker

Original

Right Cab Corner

Not Applicable

Right Quarter Panel





Original

Right Bedside

Not Applicable


Cladding / Mirror Housing

Original



Structural Inspection

True360 Structural inspection checks the following components for any evidence of structural damage. Structural damage is commonly found in welds that have been torn, separated, or re-welded, as well as body / fiberglass filler, physical damage, or areas of previous repair in relation to the inner / outer pillars. Please be aware, this report only determines if any damage has occurred and does not pass judgement on severity of damage or degree of repair.




Engine Bay Underhood (Structural)

	Meets True360 Structural Standards
Core Support	✓
Left Strut Tower / Apron	✓
Right Strut Tower / Apron	✓
Cowl Panel / Firewall	✓
Left Frame Rail	✓
Right Frame Rail	✓
Front Cross Member	✓

Inner Body Inspection

A. Pillar Left
 B. Pillar Left
 C. Pillar Left
 D. Pillar left
 Left Structural Rocker
 A. Pillar Right
 B. Pillar Right
 C. Pillar Right
 D. Pillar Right
 Right Structural Rocker
 Left Rear Strut Tower/Wheel
 Housing
 Right Rear Strut Tower/Wheel
 Housing



Rear Body Panel
Bracket / Bracing
Left Quarter Panel
Right Quarter Panel
Roof

OF INTEGRITY

2023 BMW 4 Series 430i xDrive

WBA73AV04PFN89689

3,715 Miles

True360, acting upon the findings of the assigned insp awarded this vehicle a Certificate of Integrity. This cert

the report findings. Please review the Comprehensive Condition Report to review the findings that designate:

08/31/2023

Minor Cosmetic Repairs



CHIEF EXECUTIVE OFFICER