

KULCHYTSKY

INVOICE

Invoice #: 342846

Tag #: 5700



BMW Tucson

855 W. Wetmore Rd.
Tucson, AZ 85705
Phone: (520) 748-1333
Fax: (520) 748-0716
www.bmw-tucson.com

Home: [REDACTED] Bus: [REDACTED]

Cell: [REDACTED] Email: [REDACTED]

Customer #: 6918357

@gmail.com | home

Service Advisor: 3969 JAYME LARSON

| COLOR | YEAR | PROD. DATE | WARR. EXP. | MAKE/MODEL | VIN | LICENSE | MILEAGE IN | MILEAGE OUT |
|-----------|------|------------|------------|---------------|-------------------|---------|---------------|---------------|
| BLACK | 23 | | | BMW 4-SERIES | WBA73AV04PFN89689 | | 20140 | 20141 |
| 27NOV24 D | | | | WAIT 15 JUL25 | | 12JUL25 | 12:38 12JUL25 | 14:21 12JUL25 |

OPTIONS: SOLD-STK: PFN89689 DLR: ENG: 2.0L 4 CYL TRN-A

We are a proud retailer of Original Equipment (OE) parts, sourced from the vehicle manufacturer and backed by its limited warranty.

We also offer high quality non-OE parts that are suitable for your vehicle and fit all budgets and needs. If you have chosen a non-OE part, it will be identified on your invoice as "AP". These non-OE (AP) parts are not sourced from the vehicle's manufacturer or covered by its warranty. Non-OE parts come with a limited warranty backed by AutoNation and/or the parts manufacturer.

STAY CONNECTED - Take control of your BMW from virtually anywhere with MYBMW app, which includes booking your next service appointment from the palm of your hand.

LINE OPCODE TECH TYPE HOURS

9/32NDS

61531BMPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: (N/C) 0.00

maint performed multi point inspection

ESTIMATE: 0.00

12JUL25 12:38 SA: 3969

LIST NET TOTAL

(N/C)

0.00



WARRANTY STATEMENT AND VEHICLE INSPECTION RIGHTS: PLEASE SEE THE TERMS ON THE REVERSE

SIDE OF THIS REPAIR INVOICE.
CALL/TEXT AUTHORIZATION: YOU HEREBY AUTHORIZE US TO MAKE RECURRING CALLS, TEXTS, AND TRANSMIT VOICEMAILS TO YOU AT YOUR PHONE NUMBER(S), INCLUDING BY USE OF AN AUTOMATED SYSTEM, REGARDING SALES, AND/OR SERVICE OF YOUR VEHICLE. YOU UNDERSTAND YOUR AGREEMENT IS NOT A CONDITION OF PURCHASING GOODS OR SERVICES AND YOU MAY OPT OUT YOUR PHONE NUMBER(S) BY NOTIFYING YOUR SERVICE ADVISOR OR TEXTING STOP TO ANY MESSAGE RECEIVED. MSG & DATA RATES MAY APPLY.
If we receive payments related to the goods or services provided hereunder from any third party (e.g., a check under a service contract), you agree that we may retain all such monies as if same was a payment from you and apply such funds to any outstanding indebtedness of yours. You hereby grant us a power of attorney to endorse or otherwise sign your name and to deposit such funds into the dealership's account to carry out the intent of this provision.
By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received or had the opportunity to inspect any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.

CUSTOMER SIGNATURE

DATE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

| SHOP SUPPLY AND ENVIRONMENTAL SERVICE CHARGES: | LABOR AMOUNT | 0.00 |
|--|------------------------|------|
| We may charge shop supply costs of 18.5% of the total cost of labor, not to exceed \$59.95 in addition, we may charge you a fee for hazardous waste disposal related to the servicing of your vehicle. | PARTS AMOUNT | 0.00 |
| | GAS, OIL, LUBE | 0.00 |
| | SUBLET AMOUNT | 0.00 |
| | MISC. CHARGES | 0.00 |
| | TOTAL CHARGES | 0.00 |
| | LESS INSURANCE | 0.00 |
| | SALES TAX | 0.00 |
| | PLEASE PAY THIS AMOUNT | 0.00 |

TOTALS

Customer Copy

Page 2 of 2

DealerCAP 2023 CON GROUP, LLC (BAY23) SERVICE INVOICE TYPE 2 - VEHICLE WARRANTY, "LIMITED WARRANTY" - AZ - 8/27/2017

BMW of Tucson

VEHICLE HEALTH INSPECTION

PREPARED FOR: **VLADYSLAV KULCHYTSKY**



Vladyslav Kulchytskyy



| | |
|---------|-------------------|
| DATE | July 12, 2025 |
| VIN | WBA73AV04PFN89689 |
| YEAR | 2023 |
| MAKE | BMW |
| MODEL | 4-SERIES |
| MILEAGE | 20140 |
| RO # | 342846 |

BMW of Tucson

<https://www.bmwofucson.com>

Jayne Larson
larsonj1@autonation.com

Christopher Ravare (tech)

855 W Wetmore
Tucson AZ 85705

(520) 748-1333

BMW OF TUCSON

This booklet provides a summary of the technician's inspection of your vehicle. Our goal is to service and maintain your vehicle to ensure optimal safety and extend its life. Feel free to review the technician's findings to keep you informed about your vehicle's condition. Should you have any questions about the technician's findings, don't hesitate to ask your Service Advisor to clarify. The better educated you are about your vehicle's operation and condition, the greater the likelihood that your vehicle will be a pleasure to drive. We continually strive to offer our customers the best possible experience through ongoing training in your vehicle's operation and maintenance. We are not satisfied until you are completely satisfied.

BMW VEHICLE CONDITION REPORT

Name: KULCHYTSKY, VLADYSLAV RO# 342846

Date: 07/12/2025

Mileage in: 20140

Mileage out:

Plate number:

State: NH

VIN: WBA73AV04PFN89689

● Very Good ○ May Need Future Attention ● Needs Immediate Attention

UNDER THE CAR

| | | | |
|--|---|---|--|
| 1. Oil leaks | ✓ | | |
| 2. Coolant leaks | ✓ | | |
| 3. Brake hydraulic lines, visual inspection | ✓ | | |
| 4. Fuel leaks | ✓ | | |
| 5. Exhaust system, leaks and mounting | ✓ | | |
| 6. Engine/transmission mounts | ✓ | | |
| 7. Suspension and shock absorbers | ✓ | | |
| 8. Steering components | ✓ | | |
| 9. Drive shaft/guibo clutch | ✓ | | |
| 10. Brake pads/rotors - front | ✓ | | |
| 11. Brake pads/rotors - back | ✓ | ✓ | |
| 12. Tire pressure and condition, including spare | ✓ | | |

UNDER THE HOOD

| | | | |
|---|---|--|--|
| 13. Engine oil level | ✓ | | |
| 14. Brake and clutch hydraulic fluid level | ✓ | | |
| 15. Coolant level and antifreeze protection | ✓ | | |
| 16. Power steering fluid level | ✓ | | |
| 17. Battery inspection | ✓ | | |
| 18. Windshield washer fluid level | ✓ | | |
| 19. Condition of coolant hoses and clamps | ✓ | | |
| 20. Condition and adjustment of belts | ✓ | | |

CAR EXTERIOR

| | | | |
|--|---|--|--|
| 21. Operation of all lights and signals | ✓ | | |
| 22. Body, paint, trim and glass (use diagram at upper right) | ✓ | | |
| 23. Operation of central locking system | ✓ | | |
| 24. Windshield wiper operation | ✓ | | |

ROAD TEST

| | | | |
|--|---|--|--|
| 25. Brake performance, including parking brake | ✓ | | |
| 26. Transmission shifting | ✓ | | |
| 27. Clutch operation (if equipped) | ✓ | | |
| 28. Gauges, warning lights, horn, wipers/washers | ✓ | | |
| 29. Heating and air conditioning performance | ✓ | | |
| 30. Seat belts | ✓ | | |
| 31. Wheel and tire inspection | ✓ | | |

TIRE TREAD DEPTH (32")

32. Tire tread depth at all 4 corners

LF ☒ 6

LR ☒ 9




☒ 5 RF

☒ 9 RR



More about BMW

bmwusa.com
1-800-334-4BMW



Comments

Center Signature

Client Signature

Technician Analysis

Key Information

| Brakes | Fluids |
|---|---|
| <div data-bbox="99 478 131 510"></div> <div data-bbox="207 487 594 543">Brake pads/rotors - front (mm) 8 mm</div> <div data-bbox="207 550 594 606">Brake pads/rotors - back (mm) 5 mm</div> <div data-bbox="207 613 617 669">Brake performance, including parking brake Good</div> | <div data-bbox="748 472 781 504"></div> <div data-bbox="863 478 1299 510">Engine oil level Good</div> <div data-bbox="863 518 1299 575">Brake and clutch hydraulic fluid level Good</div> <div data-bbox="863 583 1299 640">Coolant level and antifreeze protection Good</div> <div data-bbox="863 648 1299 705">Windshield washer fluid level Good</div> |
| Tires | Battery |
| <div data-bbox="99 764 131 795"></div> <div data-bbox="207 777 594 833">Left front tire tread depth (mm) (32) 6 /32</div> <div data-bbox="207 840 594 896">Right front tire tread depth (mm) (32) 5 /32</div> <div data-bbox="207 903 594 959">Right rear tire tread depth (mm) (32) 9 /32</div> <div data-bbox="207 966 594 1022">Left rear tire tread depth (mm) (32) 9 /32</div> | <div data-bbox="748 774 781 806"></div> <div data-bbox="863 783 1286 814">Battery inspection Good</div> |

CONDUCTED BY:

Christopher Ravare

INITIAL CUSTOMER REQUESTS

| Description | Price | Approved |
|--|-------|-------------------------------------|
| 0000105 - Standard Scope due per cbs | 0.00 | <input checked="" type="checkbox"/> |
| 0000610 - Engine Oil Service due per cbs | 0.00 | <input checked="" type="checkbox"/> |
| CUSTOMER STATES DRIVERS FRONT SEAT LEATHER IS LOOSE AT EXTENSION. CHECK AND ADVISE | 0.00 | <input checked="" type="checkbox"/> |
| Multi Point Inspection Included | 0.00 | <input checked="" type="checkbox"/> |

ADDITIONAL SERVICE RECOMMENDATIONS

FAILED - CRITICAL CONCERNS

| Description | Price | Approved | INFO |
|-------------|-------|----------|------|
|-------------|-------|----------|------|

CAUTION - NEEDS ATTENTION SOON

| | |
|--------------|-------------|
| Subtotal: | 0.00 |
| ShopFees | 0.00 |
| SalesTax | 0.00 |
| TOTAL | 0.00 |

KNOW YOUR VEHICLE

BMW of Tucson wants our customers to have the necessary information to make informed decisions regarding vehicle repair and maintenance. You have numerous references available to assist with this process including your Service Advisor: **Jayme Larson**. To help you start, we've included the following information specific to the findings of your vehicle inspection conducted by **Christopher R.** An educated customer is a happier customer and that's our goal at **BMW of Tucson**.

View all media for this Repair Order by clicking [here](#)

0000105 - Standard Scope

0000610 - Engine Oil Service

SEATS

MULTI-I Multi Point Inspection Included